



Traylor Bros., Inc. Crane Audit

Equipment #:

A-75

Job # / Location:

Other (see below)

Al Larson boat yard

Conducted on:

4/1/15, 1:28 PM


Prepared by:


Chris Chartrey

Score:

115/140 - 82.14%

Audit - 115/140 - 82.14%

Question	Response	Details
Crane Information:		Score:(115/140) 82.14%
Description:	Other	
	American Clyde 28	
<div><p>Appendix 1</p></div>		
Hour Meter:	566	
Safety:	Safe	
Service interval meets TBI requirements:	Yes	
Paint Condition:	71-80% Avg Wear	
Sheet Metal / Structure:	81-90% Normal Wear / Rebuilt	
General Appearance:	71-80% Avg Wear	
Operator inspections performed:	Safe	
Catwalks, ladders, access, and handrails:	SAT	
Historical data / regulatory documents:	SAT	
Boom Chords & Lacing:	Safe	

Question	Response	Details
Wire Rope Condition:	At Risk	Cable needs rewrapped.
 <p>Appendix 2</p>		
Lubrication:	SAT	
Additional Comments:		

Media



Appendix 1



Appendix 2